

# TENNESSEE DEPARTMENT OF TRANSPORTATION EROSION PREVENTION/SEDIMENT CONTROL INSPECTION REPORT

TDOT EPSC INSPECTION FORM Rev. Feb 2010

Reason For Inspection:

1st Weekly

2nd Weekly

|  |   |  |  |   |   |                             |                             |                             |                             |             | DATE: //-   | .10.11                                       |
|--|---|--|--|---|---|-----------------------------|-----------------------------|-----------------------------|-----------------------------|-------------|---|--|
| State Route  | (SR) / US Rou   | te or Road Na  | me and De  | scription:  |   |                             | Are correcti                | ve actions                  | required by I               | ihis inspec | lion report (Y/N):                                  |  |
|  |   | Wolf   | River Blvd.  |   |   |                             |                             |                             | No                          |             |   |  |
| County(ies):<br>Sh   | relby   | TDOT PIN:<br>1016  | 1  | NPDES Per<br>T  | mil (NOC)<br>NR153299   |                             | Number of I<br>Corrective A |                             | Number of F<br>Corrective A |             | Number of New<br>Sediment Releases:                 | Number of Un-Corrected<br>Sediment Releases: |
| TDOT Cons<br>7994-   | Iruction No.:<br>1535-54  | TDOT Contrac   | ct No.:  | Contractor:<br>Acuff  | Enterprises   | s Inc.                      | 0                           |                             | 0                           |             |   |  |
| prepared und<br>designed to a<br>information p<br>manage the s<br>information, I<br>of erosion an  | or penally of law last my direction of assure that qualifuresented. Based system, or those cerify that insped sediment controllers. | or supervision in<br>ied personnel p<br>I on my inquiry<br>persons directly<br>ctions of storm<br>rols have been | n accordance<br>roperly gally<br>of lhe person<br>y responsible<br>waler discha<br>performed a | e with a syste<br>ered and eva<br>n or persons<br>e for gatherin<br>arge points (c<br>s recorded in | em<br>aluated<br>who<br>ig the<br>outfalls), and<br>a the table |                             | EPSC Inspe                  | d "Jerry" S                 | tanfill<br>itle (print or   |             | Signature:  Signature:                              | Harful                                       |
| above. I certify that erosion and sediment controls in the drainage area of the identified outfall where installed as planned and designed in working order as recorded in the table above. I am aware that there are significant penalties for submitting false information, including the possibility of fine and impresonment for knowing violations. |   |  |  |   | order as<br>allies for  | COG EPS<br>(print or ty     | C Project Ma<br>pe):        |                             |                             |             | Signature on  | Rent of 3                                    |
|  |   | TDOT EPSC  |  |   |   |                             |                             |                             |                             |             | L   | V  |
| Dale   | Day of Week   | Predicted<br>Precipitation<br>(%)  | Rainfall<br>Gauge 1<br>(in)  | Rainfall<br>Gauge 2<br>(in)   | Rainfall<br>Gauge 3<br>(in)                                     | Rainfall<br>Gauge 4<br>(in) | Rainfall<br>Gauge 5<br>(in) | Rainfall<br>Gauge 6<br>(in) | Duration<br>(hr)            | NO          | ntractor Agrees with<br>or YES<br>lain and initial: | Inspection Report:                           |
| 11.7.11  | Sunday<br>Monday  | 10   |  |   | N/A<br>N/A  | N/A<br>N/A                  | N/A<br>N/A                  | N/A<br>N/A                  |                             | · ontfal    | A /   | OIT. conflict with                           |
| 11.8.11  | Tuesday   | 20   |  |   | N/A   | N/A                         | N/A                         | N/A                         |                             | T.          | prop insule   | awon at 11 the                               |
| 11.9.11  | Wednesday   | 2.0  |  |   | N/A   | N/A                         | N/A                         | N/A                         |                             | 141         |   |  |
| 11.10.11   | Thursday  | 0  | 0.15   | 0.10  | N/A   | N/A                         | N/A                         | N/A                         |                             |             |   |  |
| 11.11.11   | Friday  | 0  |  |   | N/A   | N/A                         | N/A                         | N/A                         |                             |             |   |  |
| 11-12-11   | Salurday  | 0  |  |   | N/A   | N/A                         | N/A                         | N/A                         |                             |             |   |  |
| 11.13.11   | Sunday  | 10   |  |   | N/A   | N/A                         | N/A                         | N/A                         | <b> </b>                    | <u> </u>    |   |  |
|  | Monday  |  |  |   | N/A   | N/A                         | N/A                         | N/A                         |                             |             |   |  |

Predicted Precipitation Source:

www.weather.com

Page 1 of 7

(Additional pages may be attached, if needed)

|   | ;;;;;;   | THI   | 57    | <b>.</b>  |  |
|---|----------|-------|-------|-----------|--|
| 6 | 3        | LCU.  | TUR   |           |  |
|   | 3        | - 0.7 | 7     |           |  |
| 1 | <b>\</b> | 179   | R. 3. | <i>y.</i> |  |

| State/US Route or Road Name: | Wolf River Blvd. | TDOT Construction No.: | 79954-3537-54 | TDOT Contract No.: |
|------------------------------|------------------|------------------------|---------------|--------------------|
|                              |                  |                        |               |                    |

| Date | 11/10/2011 |
|------|------------|
|      |            |

|                |             |             |   |  | Date of  | Existing           |                    |   |
|----------------|-------------|-------------|---|--|--|--------------------|--------------------|---|
| Outfall Name   | Rain        | Approx.     | LT, RT or                               | Date Last  | Stabilization  | EPSC               | Current            |   |
| or Station No. | Gage<br>No. | Station No. | Centerline                              | Disturbed  | and Code   | Control            | Condition          | Corrective Action(s) or Comments                    |
| 1              | 140.        | From / To   |   |  | T = Temp.  | Measure            | Codes*             |   |
|                |             |             |   |  | P = Perm.  | Codes*             |                    |   |
|                |             |             |   |  |  | 20000000 M2-90 CMA | Photographics (Co. | Weekly cleaning will be required, until further     |
| 1              | 1           | 14+14       | LT                                      | 11/10/2011   |  | 22,35              | FM                 | notice.   |
|                |             |             |   | 100 AC 400 AC 40 |  | 2007               | 71774-7            | Const. of RCBC Pedestrian Underpass in              |
| 1A             | 1           | 21+50       | RT                                      | 11/10/2011   |  | 41                 | FM                 | progress.   |
| 1              |             |             | 600077                                  |  | 500 TO 100 TO 10 |                    | NOVE SE            |   |
| 1B             | 1           | 22+00       | RT                                      | 11/10/2011   |  | 41                 | FM                 | Backfilling RCBC in progress.                       |
| 40             | 1           | 04.00       |   | 44/7/0044  |  |                    |                    | Corrections have been made. Monitoring              |
| 1C             | 1           | 21+00       | LT                                      | 11/7/2011  | T = 10-6-11  | 12,15,35,41        | FM                 | BMP's in place.                                     |
| 2A             | 1           | 33+50       | LT,CL                                   | 11/10/2011   |  | 10 15 16 04        | FM                 | Manitaring DMDIa in place                           |
|                |             | 33+30       | LI,CL                                   | 11/10/2011   | 26-38  | 12,15,16,24        | FIVI               | Monitoring BMP's in place.                          |
|                |             |             |   |  |  |                    |                    | Weekly cleaning for stream crossing required, until |
| 2B             | 1           | 35+50       | LT                                      | 11/10/2011   |  | 16,24              | FM                 | further notice.                                     |
| 3              | 1           | 34+50       | LT                                      | 10/27/2011   |  | 16                 | FM                 | Monitoring BMP in place.                            |
|                |             |             | 300000000000000000000000000000000000000 |  |  |                    |                    |   |
| 4              | 1           | 40+00       | RT                                      | 11/7/2011  | T = 10-24-11   | 15,16,43           | FM                 | Monitoring BMP's in place.                          |
| 5.             |             | 40.00       | DT                                      | 40/04/0044   |  | 10.00              |                    |   |
| 5A             | 1           | 49+00       | RT                                      | 10/24/2011   |  | 16,33              | FM                 | Monitoring BMP's in place.                          |
| 5B             | 1           | 50+00       | RT                                      | 10/24/2011   |  | 9,16,33            | FM                 | Monitoring BMP's in place.                          |
|                | '           | 55.00       | 131                                     | 10/24/2011   |  | 3,10,33            | 1-101              | I widilitating bivin s in place.                    |

## **EROSION AND SEDIMENT CONTROL MEASURE CODES**

|    | EROS                                  | ON A | ND SEDIMENT CONTROL MEASURE               | COD      | ES  |              | CONDITION CODES                |
|----|---------------------------------------|------|---|----------|---|--------------|--------------------------------|
| 1  | Temporary Silt Fence / Filter Barrier | 15   | Temporary seeding with Mulch              | 29       | Excess Dirt Removed from Rdwy. Daily      | M            | Maintenance                    |
| 2  | Temporary Diversion Berm or Ditch     | 16   | Temporary Mulch                           | 30       | Haul Roads Dampened for Dust Control      | U            | Upgrade Needed (Failure Noted) |
| 3  | Temporary Slope Drain                 | 17   | Erosion Control Blanket                   | 31       | Ditch Liner                               | R            | Replacement Needed             |
| 4  | Rock Check Dams                       | 18   | Flexible Channel Liner                    | 32       | Rock Sift Screen                          | FM           | Future Maintenance             |
| 5  | Brush Barrier                         | 19   | Catch Basin / Storm Inlet Protection      | 33       | Temporary Silt Fence with Backing         | С            | Cleaning Needed                |
| 6  | Sediment Removal                      | 20   | Riprap Outlet Structure                   | 34       | Enhanced Silt Fence                       | 1            | Increase Measures              |
| 7  | Straw Bale Check                      | 21   | Riprap Energy / Velocity Dissipater       | 35       | Sediment Tube                             | W            | Too Wet to Work Conditions     |
| 8  | Sand Bags                             | 22   | Curb, Gutter, or Storm Sewer Protection   | 36       | Sediment Dam                              | RO           | Repeat Occurrence              |
| 9  | Sediment Trap / Basin                 | 23   | Temporary at Construction Exit / Entrance | 37       | Concrete Washout, other pollution Issues  | SR           | Sediment Release               |
| 10 | Temp Sediment Filter Bag / Dewatering | 24   | Temporary Stream Crossing                 | 38       | Berm (soil, riprap, rock)                 | FS           | Final Stabilized               |
| 11 | Polyethylene Sheeting                 | 25   | Turbidity Barrier / Silt Boom             | 39       | Gabion                                    | S            | Stable (No Action Needed)      |
| 12 | Machined Rip Rap                      | 26   | Temporary Stream Diversion                | 40       | Sheet Pilling                             | Other (O31): |                                |
| 13 | Geotextile                            | 27   | Preserve Natural Resource / Buffer Zone   | 41       | Haul Road                                 | Other (O#2): |                                |
| 14 | Permanent Seeding with Mulch or Sod   | 28   | Mineral Aggregate Base on Subgrade        | 42<br>43 | Bridge Construction<br>Stream Realignment | Other (O#3): |                                |

| Stat | e/US Route | or Ro |
|------|------------|-------|
|      |            |       |

| State/US | Route | or Road | Name: |
|----------|-------|---------|-------|
|----------|-------|---------|-------|

Wolf River Blvd.

| TDOT | 0    |       |     |      |
|------|------|-------|-----|------|
| 1001 | Cons | ırucı | Ion | NO.: |

|  | 37-54 |
|--|-------|
|  |       |

| OT Contract No.: | <b>TDOT Contract</b> | No.: |  |
|------------------|----------------------|------|--|
|------------------|----------------------|------|--|

**CONDITION CODES** 

| Date | 11/10/2011 |
|------|------------|
|      |            |

| Outfall Name or Station No. | Rain<br>Gage<br>No. | Approx.<br>Station No.<br>From / To | LT, RT or<br>Centerline | Date Last<br>Disturbed | Date of Stabilization and Code T = Temp. P = Perm. | Existing EPSC Control Measure Codes* | Current<br>Condition<br>Codes* | Corrective Action(s) or Comments  |
|-----------------------------|---------------------|-------------------------------------|-------------------------|------------------------|--|--------------------------------------|--------------------------------|---|
| 50                          | 1                   | 44.00                               | 1.7                     | 44/7/0044              |  | 40.04.00                             |                                | Weekly cleaning for stream crossing required. (BMP's incomplete @ New       |
| 5C                          | 1                   | 44+00                               | LT                      | 11/7/2011              |  | 16,24,33                             | FM                             | Channel Realignment. See Photo)   |
| 6                           | 1                   | 56+00                               | LT                      | 10/24/2011             |  |                                      | FM                             | Pond has been drained. Currently Stable.                                    |
| 7                           | 1                   | 60+00                               | RT                      | 10/24/2011             |  | 16, 33                               | FM                             | Currently Stable, Monitoring BMP's.   |
| 8A                          | 1                   | 73+00                               | RT                      | 11/10/2011             |  | 16,24,42                             | FM                             | Weekly cleaning for stream crossing will be required, until further notice. |
| 8B                          | 2                   | 75+50                               | RT                      | 9/29/2011              |  | 16,24,35,41                          | FM                             | Currently Stable, Monitoring BMP's.   |
| 8C                          | 1                   | 71+00                               | LT                      | 11/10/2011             |  | 16,35,42                             | FM                             | Active construction zone. Monitoring BMP's.                                 |
| 8D                          | 2                   | 75+50                               | Ľ                       | 10/3/2011              | T = 10-3-11  | 16,35,42                             | FM                             | Monitoring BMP's. Weekly watering required until seed establishes.          |
| 8E                          | 1                   | 71+50                               | LT                      |                        |  |                                      |                                | The area has not been disturbed.  |
| 9A                          | 2                   | 80+00                               | RT                      | 9/29//11               | T = 10-3-11  | 6,15,33,35                           | FM                             | Weekly watering required until seed establishes.                            |
| 9B                          | 2                   | 80+00                               | LT                      | 9/29//11               | T = 10-3-11  | 15,16,17,,35                         | FM                             | Weekly watering required until seed establishes.                            |

## **EROSION AND SEDIMENT CONTROL MEASURE CODES**

### 1 Temporary Silt Fence / Filter Barrier Temporary Seeding with Mulch Excess Dirt Removed from Rdwy. Daily M Maintenance 2 Temporary Diversion Berm or Ditch Temporary Mulch 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) 3 Temporary Slope Drain 17 Erosion Control Blanket 31 Ditch Liner Replacement Needed 4 Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen FM Future Maintenance 5 Brush Barrier 19 Catch Basin / Storm Inlet Protection Temporary Silt Fence with Backing С Cleaning Needed 6 Sediment Removal 20 Riprap Outlet Structure 34 Enhanced Silt Fence Increase Measures 7 Straw Bale Check 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube W Too Wet to Work Conditions 8 Sand Bags 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues SR Sediment Release 10 Temp Sediment Filter Bag / Dewatering 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) Final Stabilized 11 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) 12 Machined Rip Rap 26 Temporary Stream Diversion 40 Sheet Pilling Other (O31): 13 Geotextile 27 Preserve Natural Resource / Buffer Zone 41 Haul Road Other (O#2): 14 Permanent Seeding with Mulch or Sod 28 Mineral Aggregate Base on Subgrade **Bridge Construction** Other (O#3):

| State/US |
|----------|
|          |

Route or Road Name: V

| No  | lf | Riv | /er | R | hvd |
|-----|----|-----|-----|---|-----|
| vvu | 11 |     |     | D | wu. |

TDOT Construction No.:

79954-3537-54

TDOT Contract No.:

| Date |   | 11/10/2011 |  |
|------|---|------------|--|
|      | TO SEE ST. 1971 - 1971 |            |  |

| Outfall Name or Station No. | Rain<br>Gage<br>No. | Approx.<br>Station No.<br>From / To | LT, RT or<br>Centerline | Date Last<br>Disturbed     | Date of Stabilization and Code T = Temp. P = Perm. | Existing EPSC Control Measure Codes* | Current<br>Condition<br>Codes* | Corrective Action(s) or Comments  |
|-----------------------------|---------------------|-------------------------------------|-------------------------|----------------------------|--|--------------------------------------|--------------------------------|---|
| 9C                          | 2                   | 79+50                               | LT                      | 9/29/2011                  | T = 10-03-11                                       | 15,16,20,33                          | FM                             | Weekly watering required until seed establishes.                        |
| 10A                         | 2                   | 85+00                               | RT                      | 9/29/2011                  |  | 15,16,35,41                          | FM                             | Monitoring BMP's in place.  |
| 10B                         | 2                   | 85+00                               | RT                      | 9/29/2011                  |  | 15,16,35,41                          | FM                             | Monitoring BMP's in place.  |
| 10C                         | 2                   | 85+50                               | LT                      | 11/7/2011                  |  | 15,16,35,41                          | FM                             | Monitoring BMP's in place.  |
| 10D                         | 2                   | 84+50                               | LT                      | 11/7/2011                  |  | 15,16,35,41                          | FM                             | Monitoring BMP's in place.  |
| 11A                         | 2                   | 92+50                               | RT                      | 11/7/2011                  |  | 35,41                                | FM                             | Monitoring BMP's in place.  |
| 11B                         | 2                   | 92+50                               | LT                      | 10/6/2011                  |  | 10,32,35,41                          | FM                             | Remove forms when accessible. See photo                                 |
| 11C                         | 2                   | 92+00                               | LT                      | 10/6/2011                  |  | 10,32,35,41                          | FM                             | Remove forms when accessible. See photo                                 |
|                             | 1                   | 11+28                               | LT                      | 11/10/2011                 |  | 19,35                                | FM                             | Daily cleaning is required, until further notice.  See Photo            |
| 47                          | 1                   | 13+40                               | RT                      | 11/10/2011                 |  | 23,29,30                             | FM                             | Daily cleaning will be required, until further notice.                  |
|                             | 1                   | 107+75<br><b>FROSIO</b> I           | CL<br>N AND SEDIME      | 11/10/2011<br>NT CONTROL M | IEASURE CODES                                      | 23,29,30                             | FM                             | Daily cleaning will be required, until further notice.  CONDITION CODES |

### **EROSION AND SEDIMENT CONTROL MEASURE CODES**

### Temporary Silt Fence / Filter Barrier 15 Temporary Seeding with Mulch 29 Excess Dirt Removed from Rdwy. Daily М Maintenance 2 Temporary Diversion Berm or Ditch 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) Temporary Slope Drain 3 17 Erosion Control Blanket 31 Ditch Liner R Replacement Needed Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen FM **Future Maintenance** 5 **Brush Barrier** 19 Catch Basin / Storm Inlet Protection 33 Temporary Silt Fence with Backing С Cleaning Needed 6 Sediment Removal 20 Riprap Outlet Structure 34 Enhanced Silt Fence Increase Measures 7 Straw Bale Check 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube W Too Wet to Work Conditions 8 Sand Bags 22 Curb, Gutler, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues SR Sediment Release 10 Temp Sediment Filter Bag / Dewatering Berm (soil, riprap, rock) 24 Temporary Stream Crossing 38 FS Final Stabilized Polyethylene Sheeting 11 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) 12 Machined Rip Rap 26 Temporary Stream Diversion 40 Sheet Pilling Other (O31): Geotextile 27 13 Preserve Natural Resource / Buffer Zone 41 Haul Road Other (O#2): 14 Permanent Seeding with Mulch or Sod 28 Mineral Aggregate Base on Subgrade 42 **Bridge Construction** Other (O#3):

| State/US Route or Road | Name: |
|------------------------|-------|
|                        |       |

Wolf River Blvd.

TDOT Construction No.:

79954-3537-54

TDOT Contract No.:

| Date | 11/10/2011 |  |
|------|------------|--|
|      |            |  |

| Outfall Name   | Rain | Approx.          | LT, RT or      | Date Last    | Date of<br>Stabilization | Existing<br>EPSC | Current   |  |
|----------------|------|------------------|----------------|--------------|--------------------------|------------------|-----------|--|
| or Station No. | Gage | Station No.      | Centerline     | Disturbed    | and Code                 | Control          | Condition | Corrective Action(s) or Comments                       |
| *(Existing     | No.  | From / To        |                |              | T = Temp.                | Measure          | Codes*    |  |
| Structure)     |      |                  |                |              | P = Perm.                | Codes*           |           |  |
| * 109+51       | 2    | East side of WRB | RT             | 11/10/2011   |                          | 19,22            | FM        | Daily cleaning will be required, until further notice. |
| 100.01         |      | South side of    | 111            | 11/10/2011   |                          | 19,22            | 1 101     | Daily cleaning will be required, until further         |
| * 109+11       | 2    | Farmington       | RT             | 11/10/2011   |                          | 19,22            | FM        | notice.  |
|                |      | North side of    |                |              |                          | ,                |           | Daily cleaning will be required, until further         |
| * 12+80        | 1    | WRB              | LT             | 11/10/2011   |                          | 19,22            | FM        | notice.  |
|                |      | Walking Trail    |                |              |                          |                  |           |  |
|                | 1    | 36+00            | LT             | 7/20/2011    | T = 7-20-11              | 5,35             | FM        | Currently stable, Monitoring BMP's                     |
|                |      | 04- 00-50 01     | 1.7            | 7/00/0044    | T 004.44                 | 40               |           | 0 " 111  |
|                | 1    | Sta. 29+50 Slope | LT             | 7/20/2011    | T= 9-01-11               | 16               | FM        | Currently stable.                                      |
|                |      | Sta. 13+40 -     |                |              |                          |                  |           | Haul roads dampened frequently for dust                |
|                |      | Sta. 107+75      | LT, RT or CL   | 10/13/2011   |                          | 30               | FM        | control, until further notice.                         |
|                | _    | 70.50 400.40     | DT             | 0/00/0044    | T - 40 00 44             | 45.40.05         | E14       |  |
| 3 3 33 33      | 2    | 76+50 - 103+46   | RT             | 9/29/2011    | T = 10-03-11             | 15,16,35         | FM        | Weekly watering required until seed establishes.       |
|                | 2    | 92+50 - 107+00   | LT             | 9/29/2011    | T = 10-03-11             | 15,16,35         | FM        | Weekly watering required until seed establishes.       |
|                |      |                  |                |              |                          |                  |           | Daily cleaning will be required, until further         |
|                | 1    | 6+75             | LT             | 11/10/2011   |                          | 19,22            | FM        | notice.  |
|                | 1    | 27+00            | RT             | 10/3/2011    | T= 10-03-11              | 15,16            | FM        | Currently stable, Monitoring BMP's                     |
|                | 1    | 34+00            | RT             | 8/25/2011    | T= 8-25-11               | 16               | FM        | Currently stable, Monitoring BMP's                     |
|                |      | EROSI            | ON AND SEDIMEN | T CONTROL ME | ASURE CODES              |                  |           | CONDITION CODES  |

## EROSION AND SEDIMENT CONTROL MEASURE CODES

### Temporary Silt Fence / Filter Barrier Temporary Seeding with Mulch Excess Dirt Removed from Rdwy. Daily M Maintenance 2 Temporary Diversion Berm or Ditch 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) 3 Temporary Slope Drain 17 **Erosion Control Blanket** 31 Ditch Liner R Replacement Needed 4 Rock Check Dams 18 Flexible Channel Liner Rock Silt Screen FM **Future Maintenance** 5 Brush Barrier 19 Catch Basin / Storm Inlet Protection 33 Temporary Silt Fence with Backing C Cleaning Needed 6 Sediment Removal 20 Riprap Outlet Structure 34 Enhanced Silt Fence -1 Increase Measures 7 Straw Bale Check 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube W Too Wet to Work Conditions 8 Sand Bags 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues SR Sediment Release 10 Temp Sediment Filter Bag / Dewatering 24 **Temporary Stream Crossing** 38 Berm (soil, riprap, rock) FS Final Stabilized 11 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) Other (O31): Machined Rip Rap 26 12 Temporary Stream Diversion Sheet Pilling 13 Geotextile 27 Preserve Natural Resource / Buffer Zone 41 Haul Road Other (O#2): 14 Permanent Seeding with Mulch or Sod 28 Mineral Aggregate Base on Subgrade **Bridge Construction** Other (O#3):

|    | OF THE ST    |  |
|----|--------------|--|
| 18 | AGRICULTURE  |  |
|    | A CONTRACTOR |  |
| ** | 1786         |  |

| 0 id Name: | Wolf River Blvd. | TDOT Construction No.: | 79954-3537-54 | TDOT Contract No.: |  |
|------------|------------------|------------------------|---------------|--------------------|--|
|            |                  |                        |               |                    |  |


Date \_\_\_\_\_11/10/2011

| Outfall Name or Station No. | Rain<br>Gage<br>No. | Approx.<br>Station No.<br>From / To | LT, RT or<br>Centerline | Date Last<br>Disturbed | Date of Stabilization and Code T = Temp. P = Perm. | Existing EPSC Control Measure Codes* | Current<br>Condition<br>Codes* | Corrective Action(s) or Comments   |
|-----------------------------|---------------------|-------------------------------------|-------------------------|------------------------|--|--------------------------------------|--------------------------------|--|
|                             | 1                   | 21+33 - 26+00                       | LT                      | 10/10/2011             | T = 10-6-11  | 15,16,35,41                          | FM                             | Weekly watering required until seed establishes.                                     |
|                             | 1                   | 21+33 - 26+00                       | RT                      | 10/10/2011             | T = 10-6-11  | 15,16,35,41                          | FM                             | Weekly watering required until seed establishes.                                     |
|                             | 1                   | 25+00                               | LT                      | 9/29/2011              | T = 10-6-11  | 15,16,33,35,41                       | FM                             | Currently stable, monitoring BMP's.  |
|                             | 11                  | 25+00                               | RT                      | 9/29/2011              | T = 10-6-11  | 15,16,33,35,41                       | FM                             | Currently stable, monitoring BMP's.  |
|                             | 1                   | 27+50                               | RT                      | 10/6/2011              | T = 10-6-11  | 15,16,33,35,41                       | FM                             | Currently stable, monitoring BMP's.  |
|                             | 1                   | 31+90                               | RT                      | 9/29/2011              | T = 10-6-11  | 15,16,35                             | FM                             | Currently stable, monitoring BMP's.  |
| 2:                          | 1                   | 15+60                               | RT                      | 9/15/2011              | T = 10-6-11  | 15,16,33,35                          | FM                             | Currently stable, monitoring BMP's. Weekly watering required until seed establishes. |
| * 108+37                    |                     | North side of<br>WRB                | LT                      | 11/10/2011             |  | 19,22                                | FM                             | Daily cleaning will be required, until further notice.                               |
|                             | 1                   | 23+00 - 26+00                       | RT                      | 9/29/2011              | T = 10-6-11  | 33,41                                | FM                             | Currently stable, monitoring BMP's.  |
|                             |                     |                                     |                         |                        | - TR-725   |                                      |                                |  |

## **EROSION AND SEDIMENT CONTROL MEASURE CODES**

### Temporary Silt Fence / Filter Barrier Temporary Seeding with Mulch Excess Dirt Removed from Rdwy. Daily M Maintenance 2 Temporary Diversion Berm or Ditch 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control U Upgrade Needed (Failure Noted) 3 Temporary Slope Drain 17 **Erosion Control Blanket** 31 Ditch Liner R Replacement Needed 4 Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen FM Future Maintenance 5 Brush Barrier 19 Catch Basin / Storm Inlet Protection Temporary Silt Fence with Backing С Cleaning Needed 6 Sediment Removal Riprap Outlet Structure 20 34 Enhanced Silt Fence Increase Measures Riprap Energy / Velocity Dissipater 7 Straw Bale Check 21 35 Sediment Tube W Too Wet to Work Conditions 8 Sand Bags 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence 9 Sediment Trap / Basin Temporary at Construction Exit / Entrance 23 37 Concrete Washout, other pollution Issues SR Sediment Release 10 Temp Sediment Filter Bag / Dewatering 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) FS Final Stabilized 11 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 S Gabion Stable (No Action Needed) Machined Rip Rap 12 26 Temporary Stream Diversion 40 Sheet Pilling Other (O31): 13 Geotextile 27 Preserve Natural Resource / Buffer Zone Haul Road Other (O#2): 41 Permanent Seeding with Mulch or Sod 28 Mineral Aggregate Base on Sub grade Bridge Construction Other (O#3):

**CONDITION CODES** 





City of Germantown 1920 S. Germantown Road Germantown, TN 38138